Company			Listing Submitted	12/30/2021	Area of state conducts work	
Petroleum Equipment Service of Wilson, Inc.	Р	Phone	(252) 237-6047		Coastal (East of I-95): Yes	
PO Box 502		Fax	(252) 237-5507		Central (West of I-95 and East of I-77): Yes	
711 S. Goldsboro St.			(,,,		Mountains (West of I-77): No	
Wilson, NC 27893	We	ebsite	www.peswilson.com		Mountains (West of Fif). No	
Comp	pliance Testin	ng and	Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No (	Overfill I	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistic	al Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No S	Spill Pre	evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tig	ghtness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No l	UST Inte	ernal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No l	UST Inte	ernal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No (	Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmental	Servic	e Firms		Other:	
Emergency Cleanup - Spill/Release:	No l	UST Co	mpliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No l	UST Eq	uipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu			Disposal and Treatment:	No		
Oil and Solvent Recycling:		Other:	•			
Soil and Water Testing Lab:	No					
Company			Listing Submitted	8/4/2020	Area of state conducts work	
Advanced Environmental Services, Inc.	Р	Phone	(336) 282-3586		Coastal (East of I-95): Yes	
PO Box 38218		Fax	(336) 282-3587		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27438		Iux	(000) 202 0001			
	We	ebsite	<u>advancedenvironmental.com</u>		Mountains (West of I-77): Yes	
Comp	pliance Testin	ng and	Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No (	Overfill	Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	Statistic	al Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	Spill Pre	evention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tig	ghtness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No l	UST Into	ernal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No l	UST Into	ernal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No (	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Fr	nvironmental	Servic	e Firms		Other:	
			andiana Canadanta	No		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Co	mpliance Consultants:	INO		
			uipment Verification:	No		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Eq		No		
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes \	UST Eq	uipment Verification:			

Company		Listing Submitted	1	Area of state conducts work	
AES of Greenville LLC	P	hone (252) 758-3311		Coastal (East of I-95): Yes	
141 S. Market Street		Fax (252) 481-5814		Central (West of I-95 and East of I-77): Yes	
Washington, NC 27889		(202) 101 0011		Mountains (West of I-77): Yes	
	Wek	osite <u>www.aes-nc.com</u>		Wouldains (West of 1-77): Tes	
Comp	oliance Testin	g and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u> S	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		ank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		JST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u> U	JST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u> C	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironmental S	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No U	JST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No U	JST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No V	Vaste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No C	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/15/2021	Area of state conducts work	
American UST Compliance Testing	P	hone (919) 777-8543		Coastal (East of I-95): Yes	
180 BPW Club Rd. A-1		Fax		Central (West of I-95 and East of I-77): Yes	
Carrboro, NC 27510				Mountains (West of I-77): Yes	
	Wek	osite		Mountains (west of 1-77). Tes	
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	-				V
Contains out Comm. To ette so	<u>Yes</u> C	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:		Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	<u>Yes</u> No	Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	<u>Yes</u> No
Corrosion Protection Design Experts:	<u>Yes</u> S				
	Yes S No S No T	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes S No S No T	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No <u>Yes</u>	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No <u>Yes</u>
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes S No S No T Yes U	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No <u>Yes</u> <u>Yes</u>	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No <u>Yes</u> No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes S No S No T Yes U Yes U	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No <u>Yes</u> <u>Yes</u> No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No <u>Yes</u> No <u>Yes</u>
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes S No S No T Yes U Yes U	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes         S           No         S           No         T           Yes         U           Yes         U           No         C	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No <u>Yes</u> <u>Yes</u> No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes No Yes No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes S No S No T Yes U Yes U No C Yes	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No Yes Yes No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes S No S No T Yes U No C Yes U nvironmental \$	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms	No <u>Yes</u> <u>Yes</u> No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	Yes S No S No T Yes U No C Yes U Yes U Yes U Yes U No C Yes U No C	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: JST Internal Inspections (Integrity Assessments): JST Internal Lining Inspections: Other:  Service Firms JST Compliance Consultants:	No Yes Yes No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes S No S No T Yes U Yes U No Yes  nvironmental S Yes U No U No W	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants: UST Equipment Verification:	No Yes Yes No No Yes No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No

Company			Listing Submitted	5/17/2021	Area of state conducts work	
Apex Engineering, PC	F	hone (301	I) 417-0200		Coastal (East of I-95): Yes	
15850 Crabbs Branch Way		Fax (301	1) 975-0169		Central (West of I-95 and East of I-77): Yes	
Suite 200		(	,		Mountains (West of I-77): Yes	
Rockville, Maryland 20855-	We	bsite <u>www</u>	v.apexcos.com		moditalits (West 61177). 163	
Comp	pliance Testir	g and Moni	itoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prever	ntion Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iver	ntory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention	on Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Γank Tightnes	ss Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	JST Internal I	Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	JST Internal L	Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
E	nvironmental	Service Firi	ms		Other:	
Emergency Cleanup - Spill/Release:	Yes	JST Compliar	nce Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:			ent Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu			sal and Treatment:	Yes		
Oil and Solvent Recycling:		Other:				
Soil and Water Testing Lab:	<u>Yes</u>					
Company			Listing Submitted	7/19/2022	Area of state conducts work	
Company  B & M WEST CONSTRUCTION CO OF TEXAS	DRAD E	hone (863	Listing Submitted	7/19/2022	Area of state conducts work	
B & M WEST CONSTRUCTION CO OF TEXAS	DBA D. F	•	3) 519-4441	7/19/2022	Coastal (East of I-95): Yes	
	DBA D. F	•		7/19/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD		<b>Fax</b> (863	3) 519-4441	7/19/2022	Coastal (East of I-95): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860	We	Fax (863	3) 519-4441 3) 519-4407 SHOUPPE.COM	7/19/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp	We pliance Testir	Fax (863 bsite DWS	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860  Comparing Line Leak Detector Testing:	We pliance Testin	Fax (863 bsite DWS g and Moni	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring ntion Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860  Comparing Line Leak Detector Testing: Containment Sump Testing:	Wepliance Testin	Fax (863 bsite DWS g and Moni Dverfill Prever Statistical Iver	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring ntion Equipment Operability Check: ntory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860  Comparison of the Compariso	We pliance Testin No No No No	Fax (863 bsite DWS g and Moni Dverfill Prever Statistical Iver	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring ntion Equipment Operability Check: ntory Reconciliation Services: on Equipment Testing:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	We pliance Testin No No No No No No	Fax (863 bsite DWS g and Moni Dverfill Prever Statistical Iver Spill Preventio Fank Tightnes	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring ntion Equipment Operability Check: ntory Reconciliation Services: on Equipment Testing: ss Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No <u>Yes</u>
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	We pliance Testin No No No No No No No No No	Fax (863 bsite DWS g and Moni Dverfill Preverticatistical Iver Spill Preventication Trank Tightness JST Internal I	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: Interpretable of Equipment Testing: Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No <u>Yes</u> No
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	We pliance Testir No	Fax (863 bsite DWS g and Moni Dverfill Preverticatistical Iver Spill Preventication Trank Tightness UST Internal I	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring ntion Equipment Operability Check: ntory Reconciliation Services: on Equipment Testing: ss Testing:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No <u>Yes</u> No No
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860  Comparison Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	We pliance Testin No	Fax (863 bsite DWS g and Moni Overfill Preverticatistical Iver Spill Preventication Trank Tightnes UST Internal	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: Interpretable of Equipment Testing: Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No Yes No No No
B & M WEST CONSTRUCTION CO OF TEXAS  209 E BADCOCK BLVD  MULBERRY, FL 33860  Comparison Automatic Line Leak Detector Testing:  Containment Sump Testing:  Corrosion Protection Design Experts:  Corrosion Protection System Repairs:  Corrosion Protection System Testing:  Leak Detection Equipment Operability Check:  Leak Detection Monitoring Services:  Line Tightness Testing:	We pliance Testir No	Fax (863 bsite DWS g and Moni Overfill Prevention Fank Tightnes JST Internal I JST Internal L Other:	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: In Equipment Testing: Inspections (Integrity Assessments): Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860  Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We pliance Testir No	Fax (863 bsite DWS g and Moni Dverfill Prever Statistical Iver Spill Preventio Fank Tightnes JST Internal I JST Internal L Dther:	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring ntion Equipment Operability Check: ntory Reconciliation Services: on Equipment Testing: ss Testing: Inspections (Integrity Assessments): Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS 1209 E BADCOCK BLVD MULBERRY, FL 33860  Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release:	We pliance Testir No	Fax (863 bsite DWS g and Moni Overfill Prever Statistical Iver Spill Preventio Tank Tightnes JST Internal I JST Internal L Other:  Service Fire JST Complian	B) 519-4441 B) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: Intory Equipment Testing: Inspections (Integrity Assessments): Lining Inspections: Inspections: Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS  209 E BADCOCK BLVD MULBERRY, FL 33860  Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Pliance Testir No	Fax (863 bsite DWS g and Moni Dverfill Prever Statistical Iver Spill Preventio Tank Tightnes JST Internal I JST Internal L Dther:  Service Fire JST Complian JST Equipme	B) 519-4441 B) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: Intory Reconciliation Services: In Equipment Testing: Inspections (Integrity Assessments): Lining Inspections: Integrity Assessments: Integr	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS 1209 E BADCOCK BLVD MULBERRY, FL 33860  Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release:	We pliance Testir No	Fax (863 bsite DWS g and Moni Dverfill Prever Statistical Iver Spill Preventio Tank Tightnes JST Internal I JST Internal L Dther:  Service Fire JST Complian JST Equipme	B) 519-4441 B) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: Intory Equipment Testing: Inspections (Integrity Assessments): Lining Inspections: Inspections: Inspections:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	We pliance Testir No	Fax (863 bsite DWS g and Moni Overfill Prevention Fank Tightnes JST Internal I JST Internal L Other:  Service Fire JST Compliar JST Equipme Waste Dispos	B) 519-4441 B) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: Intory Reconciliation Services: In Equipment Testing: Inspections (Integrity Assessments): Lining Inspections: Integrity Assessments: Integr	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes

Company		Listing Submitted		Area of state conducts work	
Bay Compliance and Testing LLC	Р	hone (757) 410-5974		Coastal (East of I-95): Yes	
P.O. Box 16628		Fax		Central (West of I-95 and East of I-77): No	
Chesapeake, VA 23328				Mountains (West of I-77): No	
	We	bsite https://baycomplianceandtesting.com/		Modificants (West of 1-77). No	
Comp	oliance Testin	g and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		ank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		JST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:		JST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No (	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No l	JST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No l	JST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No \	Vaste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No (	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	2/1/2021	Area of state conducts work	
Buckeye Elm Contracting	P	hone (888) 315-8663		Coastal (East of I-95): Yes	
PO Box 1026		Fax		Central (West of I-95 and East of I-77): Yes	
Mocksville, NC 27028				Mountains (West of I-77): Yes	
	We	bsite www.buckeye-elm.com		mountains (West of 1-77).	
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No (	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	Al-	Saill Description Facilities and Tastings		Spill Bucket Installation Repair:	No
	No S	Spill Prevention Equipment Testing:	No	opin Buokot motanation Propan.	
Corrosion Protection System Repairs:		ank Tightness Testing:	No No	UST Equipment Installation - Other:	No
Corrosion Protection System Repairs: Corrosion Protection System Testing:	No				No No
	No I	ank Tightness Testing:	No	UST Equipment Installation - Other:	
Corrosion Protection System Testing:	No l	ank Tightness Testing:  JST Internal Inspections (Integrity Assessments):	No No	UST Equipment Installation - Other: UST Equipment Repair:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No l	ank Tightness Testing:  JST Internal Inspections (Integrity Assessments):  JST Internal Lining Inspections:	No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No I No No No	ank Tightness Testing:  JST Internal Inspections (Integrity Assessments):  JST Internal Lining Inspections:	No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No I No I No I No No	Tank Tightness Testing:  JST Internal Inspections (Integrity Assessments):  JST Internal Lining Inspections:  Other:	No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Tank Tightness Testing:  JST Internal Inspections (Integrity Assessments):  JST Internal Lining Inspections:  Other:  Service Firms	No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	No N	Tank Tightness Testing:  UST Internal Inspections (Integrity Assessments):  UST Internal Lining Inspections:  Other:  Service Firms  UST Compliance Consultants:	No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Tank Tightness Testing:  UST Internal Inspections (Integrity Assessments):  UST Internal Lining Inspections:  Other:  Service Firms  UST Compliance Consultants:  UST Equipment Verification:	No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No

Company		` /	Submitted 5/14/2021	Area of state conducts work	
Cobb Environmental & Technical Services, Inc	).	Phone (662) 841-0995		Coastal (East of I-95): Yes	
P. O. Box 1602, Tupelo, MS 38802		Fax (662) 841-0810		Central (West of I-95 and East of I-77): Yes	
871 South Green Street		(502) 511 5010		Mountains (West of I-77): Yes	
Tupelo, MS 38804	W	ebsite <u>www.cobbenv.com</u>		Mountains (West of 1-77). Tes	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability C	heck: <u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	<b>UST Internal Inspections (Integrity Assessr</b>	nents): No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing \$	Submitted 1/20/2022	Area of state conducts work	
COHESION, INC		Phone (919) 233-8626		Coastal (East of I-95): Yes	
5216 YATES MILL POND RD		Fax		Central (West of I-95 and East of I-77): Yes	
RALEIGH, NC 27606					
	W	ebsite <u>WWW.COHESION-INC.COM</u>		Mountains (West of I-77): No	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability C	heck: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
				UST Equipment Repair:	No
Corrosion Protection System Testing:	No	<b>UST Internal Inspections (Integrity Assessr</b>	nents): No	OOT Equipment Repair.	
Leak Detection Equipment Operability Check:	No No	UST Internal Inspections (Integrity Assessr UST Internal Lining Inspections:	nents): No No	UST System Installation - Complete Systems:	No
					No No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:		UST System Installation - Complete Systems:	
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No	UST Internal Lining Inspections:		UST System Installation - Complete Systems: UST Piping/Sump Installation:	No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No nvironmenta	UST Internal Lining Inspections: Other:	No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No	UST Internal Lining Inspections: Other: Service Firms		UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	No No No nvironmenta Yes No	UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants:	No Yes	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Erregency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No nvironmenta Yes No	UST Internal Lining Inspections: Other:  Service Firms  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No  Yes No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No

Company			isting Submitted	12/30/2021	Area of state conducts work	
Crompco, LLC		Phone (610) 278-7203	<u> </u>		Coastal (East of I-95): Yes	
1815 Gallagher Road		Fax (610) 278-7621			Central (West of I-95 and East of I-77): Yes	
Plymouth Meeting, PA 19462		(010) 276-7021				
	W	ebsite <u>www.crompco.com</u>			Mountains (West of I-77): Yes	
Comp	oliance Testi	ng and Monitoring			<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Ope	erability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation S	Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing	g:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	<b>UST Internal Inspections (Integrity</b>	Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironmenta	I Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:		Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:		No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company		l	isting Submitted	9/24/2021	Area of state conducts work	
C-Store Services, Inc.		Phone (919) 662-0798			Coastal (East of I-95): Yes	
7129 Hidden Valley Trail		Fax (919) 662-0711			Central (West of I-95 and East of I-77): Yes	
Garner, NC 27529						
I.		,				
	W	ebsite			Mountains (West of I-77): No	
Comp		ebsite ng and Monitoring				
Comp Automatic Line Leak Detector Testing:			erability Check:	Yes	Mountains (West of I-77): No	Yes
_	oliance Testi	ng and Monitoring		Yes No	Mountains (West of I-77): No  UST Equipmment Service Contractors	Yes Yes
Automatic Line Leak Detector Testing:	oliance Testi No	ng and Monitoring Overfill Prevention Equipment Ope	Services:		Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	No Yes	ng and Monitoring  Overfill Prevention Equipment Ope Statistical Iventory Reconciliation S	Services:	No	Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No Yes No	ng and Monitoring  Overfill Prevention Equipment Ope Statistical Iventory Reconciliation S Spill Prevention Equipment Testing	Services: g:	No <u>Yes</u>	Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:	<u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No Yes No No	ng and Monitoring  Overfill Prevention Equipment Ope Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing:	Services: g:	No <u>Yes</u> No	Wountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Yes No No No	ng and Monitoring  Overfill Prevention Equipment Operatistical Iventory Reconciliation Spill Prevention Equipment Testing Tank Tightness Testing:  UST Internal Inspections (Integrity	Services: g:	No Yes No No	Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Yes No No No No No	ng and Monitoring  Overfill Prevention Equipment Operates Statistical Iventory Reconciliation Spill Prevention Equipment Testing Tank Tightness Testing:  UST Internal Inspections (Integrity UST Internal Lining Inspections:	Services: g: Assessments):	No Yes No No	Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	ng and Monitoring  Overfill Prevention Equipment Operates Statistical Iventory Reconciliation Spill Prevention Equipment Testing Tank Tightness Testing:  UST Internal Inspections (Integrity UST Internal Lining Inspections:	Services: g: Assessments):	No Yes No No	Wountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	ng and Monitoring  Overfill Prevention Equipment Ope Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity UST Internal Lining Inspections: Other:  I Service Firms	Services: g: Assessments):	No Yes No No	Wountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	ng and Monitoring  Overfill Prevention Equipment Operations Statistical Iventory Reconciliation Statis	Services: g: Assessments):	No Yes No No No oection	Wountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	No Yes No	ng and Monitoring  Overfill Prevention Equipment Ope Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity UST Internal Lining Inspections: Other:  I Service Firms UST Compliance Consultants:	Services: g: Assessments):	No Yes No No No Pection No	Wountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Yes No	ng and Monitoring  Overfill Prevention Equipment Ope Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity UST Internal Lining Inspections: Other:  I Service Firms  UST Compliance Consultants: UST Equipment Verification:	Services: g: Assessments):	No Yes No No No Dection No No	Wountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes No Yes

Company		Listing Submitted	9/28/2022	Area of state conducts work	
D. H. Griffin Wrecking Company	1	Phone (336) 214-9012		Coastal (East of I-95): Yes	
4716 Hilltop Road		Fax		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27407		. 42		Mountains (West of I-77): Yes	
	We	ebsite <u>www.dhgriffin.com</u>		Wouldains (West of 1-77). Tes	
Comp	pliance Testin	ng and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmental	l Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	· <del></del>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:		Other: Vacuum Truck			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/26/2020	Area of state conducts work	
East Coast Environmental PA		Phone (919) 772-0268	3/20/2020	Coastal (East of I-95): Yes	
3815 Junction Boulevard		•		,	
Raleigh , NC 27603		Fax		Central (West of I-95 and East of I-77): Yes	
	We	ebsite eastcoastenv.com		Mountains (West of I-77): No	
Com.				UCT Facility ment Coming Contractors	
		ng and Monitoring	Na	UST Equipmment Service Contractors	V
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:		Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
	NI-	LIOT between the constitute with Assessments.	NI.		<u>Yes</u>
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	V
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No			UST System Installation - Complete Systems: UST Piping/Sump Installation:	<u>Yes</u>
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No	UST Internal Lining Inspections: Other:		UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No nvironmental	UST Internal Lining Inspections: Other:  I Service Firms		UST System Installation - Complete Systems: UST Piping/Sump Installation:	<u>Yes</u>
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release:	No No No nvironmental <u>Yes</u>	UST Internal Lining Inspections: Other:  I Service Firms UST Compliance Consultants:		UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	<u>Yes</u>
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No nvironmental Yes Yes	UST Internal Lining Inspections: Other:  I Service Firms UST Compliance Consultants: UST Equipment Verification:	No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	<u>Yes</u>
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No No No nvironmental Yes Yes Yes	UST Internal Lining Inspections: Other:  I Service Firms  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No Yes	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	<u>Yes</u>
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No nvironmental Yes Yes Yes	UST Internal Lining Inspections: Other:  I Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes Yes	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	<u>Yes</u>

Company		Listing Submitted	2/1/2021	Area of state conducts work	
EHC Environmental		Phone (910) 843-4456		Coastal (East of I-95): Yes	
207 West Fourth Avenue		Fax (910) 843-5376		Central (West of I-95 and East of I-77): Yes	
Red Springs, NC 28377		,		Mountains (West of I-77): No	
	W	bsite			
Comp	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	Yes	Other: pandonments, Phase I ESA's, Landfarm Soil D			
Soil and Water Testing Lab:	No	Other. Januariments, Friase Februs, Landiani Con D	ізрозаі		
Con and water resting Lab.	110				
Company		Listing Submitted	7/30/2020	Area of state conducts work	
Environmental Contracting & Consulting Serv	ices, P	Phone (757) 912-2276		Coastal (East of I-95): Yes	
10 3rd Avenue		Fax		Central (West of I-95 and East of I-77): No	
Southern Shores, NC 27949				Mountains (West of I-77): No	
	W	ebsite		mountaine (voor et 177).	
Comp	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>res</u> Yes	UST Equipment Verification:	<u>res</u> <u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>res</u> <u>Yes</u>		
Oil and Solvent Recycling:	Yes	Other: tank removals and in-situ			
Soil and Water Testing Lab:		Carrotte and in situ	21000100		
	<u>Yes</u>				

Company		Listing Submitte		Area of state conducts work	
Environmental Laboratories, Inc	F	Phone (864) 370-0637		Coastal (East of I-95): Yes	
PO Box 1729		Fax (864) 752-0948		Central (West of I-95 and East of I-77): Yes	
Travelers Rest, SC 29609		(601) 102 0010		Mountains (West of I-77): Yes	
	We	ebsite <u>www.elabsinc.net</u>		Wouldains (West Of 1-77). Tes	
Comp	pliance Testir	ng and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Eı	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	ed 1/4/2022	Area of state conducts work	
EnviroTrac Ltd.	F	Phone (336) 763-6025		Coastal (East of I-95): Yes	
7343 West Friendly Avenue		Fax		Central (West of I-95 and East of I-77): Yes	
Suite J		Tux			
Greensboro, NC 27410	We	ebsite envirotrac.com		Mountains (West of I-77): Yes	
Comp	pliance Testir	ag and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		ig and monitoring		OST Equipminent Service Contractors	
		Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No		No No		No No
Containment Sump Testing: Corrosion Protection Design Experts:	No No	Overfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	
	No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release:	No Vo  rvironmental Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No No No No No vironmental Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No Yes No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company			Listing Submitted	d 1/3/2022	Area of state conducts work	
Evo Corporation		Phone (336) 725-5844			Coastal (East of I-95): Ye	es
1703 Vargrave Street		Fax			Central (West of I-95 and East of I-77): Ye	es
Winston-Salem, NC 27107					Mountains (West of I-77): Ye	
	V	ebsite www.evocorp.ne	<u>t</u>		mountains (West of 1-77).	
Comp	oliance Test	ing and Monitoring			UST Equipmment Service Contractor	S
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipme	nt Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconcili	ation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment	Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (In	tegrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspection	ons:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmenta	I Service Firms			Other: Vacuum Truc	k Services
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultan	ts:	No		
Environmental Engineer/Geologist - Site Checks:	No	<b>UST</b> Equipment Verification	:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatm	ent:	<u>Yes</u>		
		Other	Transportation	Services		
Oil and Solvent Recycling:	<u>Yes</u>	Other:	Hansportation			
Oil and Solvent Recycling: Soil and Water Testing Lab:	<u>Yes</u> No	Otner:	Tansportation			
		Otner:	Listing Submittee		Area of state conducts work	
Soil and Water Testing Lab:		Phone (540) 563-1022			Area of state conducts work  Coastal (East of I-95): Ye	es
Company Fourstar Petroleum 1119 Beaumont Rd.		Phone (540) 563-1022			Coastal (East of I-95): Ye	
Soil and Water Testing Lab:  Company  Fourstar Petroleum		Phone (540) 563-1022 Fax (540) 362-1802	Listing Submitted		Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye	es
Company Fourstar Petroleum 1119 Beaumont Rd.	No	Phone (540) 563-1022	Listing Submitted		Coastal (East of I-95): Ye	es
Company Fourstar Petroleum 1119 Beaumont Rd. Roanoke, VA 24019	No W	Phone (540) 563-1022 Fax (540) 362-1802	Listing Submitted		Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye	es es
Company Fourstar Petroleum 1119 Beaumont Rd. Roanoke, VA 24019	No W	Phone (540) 563-1022 Fax (540) 362-1802  ebsite www.fourstarpetr	Listing Submitted		Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye	es es
Company Fourstar Petroleum 1119 Beaumont Rd. Roanoke, VA 24019  Comp	No W	Phone (540) 563-1022 Fax (540) 362-1802  ebsite www.fourstarpetring and Monitoring	Listing Submitted	d 8/4/2020	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractor	es es s
Company Fourstar Petroleum 1119 Beaumont Rd. Roanoke, VA 24019  Company  Company  Automatic Line Leak Detector Testing:	No Waliance Test	Phone (540) 563-1022 Fax (540) 362-1802  Pebsite www.fourstarpetring and Monitoring  Overfill Prevention Equipme	Listing Submitted  Occom  Int Operability Check: ation Services:	d 8/4/2020 No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractor Dispenser Meter Repair/Calibration:	es es <u>Yes</u>
Company Fourstar Petroleum 1119 Beaumont Rd. Roanoke, VA 24019  Company  Automatic Line Leak Detector Testing: Containment Sump Testing:	No Woliance Test No No	Phone (540) 563-1022 Fax (540) 362-1802  ebsite www.fourstarpetring and Monitoring  Overfill Prevention Equipme Statistical Iventory Reconcili	Listing Submitted  Occom  Int Operability Check: ation Services:	d 8/4/2020 No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractor Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	es es Yes Yes
Company  Fourstar Petroleum  1119 Beaumont Rd. Roanoke, VA 24019  Company  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No Williance Test No No No	Phone (540) 563-1022 Fax (540) 362-1802  ebsite www.fourstarpetring and Monitoring  Overfill Prevention Equipme Statistical Iventory Reconcili Spill Prevention Equipment	Listing Submitted TO.com  Int Operability Check: ation Services: Testing:	No No No	Coastal (East of I-95): Ye  Central (West of I-95 and East of I-77): Ye  Mountains (West of I-77): Ye  UST Equipmment Service Contractor  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:	es es Yes Yes Yes
Company  Fourstar Petroleum  1119 Beaumont Rd. Roanoke, VA 24019  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No  Williance Test No No No No No	Phone (540) 563-1022 Fax (540) 362-1802  ebsite www.fourstarpetring and Monitoring  Overfill Prevention Equipme Statistical Iventory Reconcili Spill Prevention Equipment Tank Tightness Testing:	Listing Submitted CO.com  Int Operability Check: ation Services: Testing: tegrity Assessments):	No No No No	Coastal (East of I-95): Ye  Central (West of I-95 and East of I-77): Ye  Mountains (West of I-77): Ye  UST Equipmment Service Contractor  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:  UST Equipment Installation - Other:	Yes Yes Yes Yes Yes Yes
Company  Fourstar Petroleum  1119 Beaumont Rd. Roanoke, VA 24019  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No  No No No No No No No No No	Phone (540) 563-1022 Fax (540) 362-1802  ebsite www.fourstarpetring and Monitoring  Overfill Prevention Equipment Statistical Iventory Reconcilis Spill Prevention Equipment Tank Tightness Testing:  UST Internal Inspections (In	Listing Submitted CO.com  Int Operability Check: ation Services: Testing: tegrity Assessments):	No No No No No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye  UST Equipmment Service Contractor  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes Yes Yes Yes
Company  Fourstar Petroleum  1119 Beaumont Rd. Roanoke, VA 24019  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No  Violiance Test  No  No  No  No  No  No  No  No  No	Phone (540) 563-1022 Fax (540) 362-1802  Pebsite www.fourstarpetroing and Monitoring  Overfill Prevention Equipment Statistical Iventory Reconciling Spill Prevention Equipment Tank Tightness Testing:  UST Internal Inspections (In UST Internal Lining Inspections)	Listing Submitted CO.com  Int Operability Check: ation Services: Testing: tegrity Assessments):	No No No No No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye  UST Equipmment Service Contractor  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes Yes Yes
Company  Fourstar Petroleum  1119 Beaumont Rd. Roanoke, VA 24019  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No  VI  Diance Test  No  No  No  No  No  No  No  No  No  N	Phone (540) 563-1022 Fax (540) 362-1802  Pebsite www.fourstarpetroing and Monitoring  Overfill Prevention Equipment Statistical Iventory Reconciling Spill Prevention Equipment Tank Tightness Testing:  UST Internal Inspections (In UST Internal Lining Inspections)	Listing Submitted CO.com  Int Operability Check: ation Services: Testing: tegrity Assessments):	No No No No No	Coastal (East of I-95): Ye  Central (West of I-95 and East of I-77): Ye  Mountains (West of I-77): Ye  UST Equipmment Service Contractor  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes
Company  Fourstar Petroleum  1119 Beaumont Rd. Roanoke, VA 24019  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No  VI  Diance Test  No  No  No  No  No  No  No  No  No  N	Phone (540) 563-1022 Fax (540) 362-1802  Lebsite www.fourstarpetring and Monitoring  Overfill Prevention Equipme Statistical Iventory Reconcili Spill Prevention Equipment Tank Tightness Testing: UST Internal Inspections (In UST Internal Lining Inspectio Other:	Listing Submitted TO.com  Int Operability Check: ation Services: Testing: tegrity Assessments): ons:	No No No No No	Coastal (East of I-95): Ye  Central (West of I-95 and East of I-77): Ye  Mountains (West of I-77): Ye  UST Equipmment Service Contractor  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:  UST Equipment Installation - Other:  UST Equipment Repair:  UST System Installation - Complete Systems:  UST Piping/Sump Installation:  UST System Removal:	Yes
Company  Fourstar Petroleum  1119 Beaumont Rd. Roanoke, VA 24019  Comp  Automatic Line Leak Detector Testing: Cortainment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Diliance Test No	Phone (540) 563-1022 Fax (540) 362-1802  Pebsite www.fourstarpetricing and Monitoring  Overfill Prevention Equipme Statistical Iventory Reconcili Spill Prevention Equipment Tank Tightness Testing: UST Internal Inspections (In UST Internal Lining Inspection Other:	Listing Submitted TO.com  Int Operability Check: ation Services: Testing: tegrity Assessments): ons:	No No No No No No	Coastal (East of I-95): Ye  Central (West of I-95 and East of I-77): Ye  Mountains (West of I-77): Ye  UST Equipmment Service Contractor  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:  UST Equipment Installation - Other:  UST Equipment Repair:  UST System Installation - Complete Systems:  UST Piping/Sump Installation:  UST System Removal:	Yes
Company  Fourstar Petroleum  1119 Beaumont Rd. Roanoke, VA 24019  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release:	No  No No No No No No No No No No No No	Phone (540) 563-1022 Fax (540) 362-1802  Tebsite www.fourstarpetricing and Monitoring  Overfill Prevention Equipme Statistical Iventory Reconcili Spill Prevention Equipment Tank Tightness Testing: UST Internal Inspections (In UST Internal Lining Inspection Other:  Il Service Firms  UST Compliance Consultant	Listing Submitted TO.com  Int Operability Check: ation Services: Testing: tegrity Assessments): ons:	No No No No No No	Coastal (East of I-95): Ye  Central (West of I-95 and East of I-77): Ye  Mountains (West of I-77): Ye  UST Equipmment Service Contractor  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:  UST Equipment Installation - Other:  UST Equipment Repair:  UST System Installation - Complete Systems:  UST Piping/Sump Installation:  UST System Removal:	Yes
Company  Fourstar Petroleum 1119 Beaumont Rd. Roanoke, VA 24019  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No  No No No No No No No No No No No No	Phone (540) 563-1022 Fax (540) 362-1802  Pebsite www.fourstarpetricing and Monitoring  Overfill Prevention Equipment Statistical Iventory Reconcilis Spill Prevention Equipment Tank Tightness Testing: UST Internal Inspections (In UST Internal Lining Inspection Other:  Il Service Firms  UST Compliance Consultan UST Equipment Verification	Listing Submitted TO.com  Int Operability Check: ation Services: Testing: tegrity Assessments): ons:	No No No No No No No	Coastal (East of I-95): Ye  Central (West of I-95 and East of I-77): Ye  Mountains (West of I-77): Ye  UST Equipmment Service Contractor  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:  UST Equipment Installation - Other:  UST Equipment Repair:  UST System Installation - Complete Systems:  UST Piping/Sump Installation:  UST System Removal:	Yes

Company		Listing Submitted	d 12/30/2021	Area of state conducts work	
Geo-Hydro Engineers, Inc.		Phone (704) 837-7174		Coastal (East of I-95): Yes	
2748 Interstate Street		Fax		Central (West of I-95 and East of I-77): Yes	
Suite A				Mountains (West of I-77): Yes	
Charlotte, NC 28208		Website <u>www.geohydro.com</u>		mountains (West of 177). Tes	
Comp	pliance Te	sting and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	d 1/3/2022	Area of state conducts work	
Geological Resources, Inc.		Dhone (704) 945 4040		Coastal (East of LOE). Voc	
		Phone (704) 845-4010		Coastal (East of I-95): Yes	
3502 Hayes Road		Fax (704) 845-4010		Central (West of I-95 and East of I-77): Yes	
·		Fax (704) 845-4012		Central (West of I-95 and East of I-77): Yes	
3502 Hayes Road		,			
3502 Hayes Road Monroe, NC 28112		Fax (704) 845-4012		Central (West of I-95 and East of I-77): Yes	
3502 Hayes Road Monroe, NC 28112		Fax (704) 845-4012  Website grienv.com	No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	No
3502 Hayes Road Monroe, NC 28112	pliance Te	Fax (704) 845-4012  Website grienv.com  sting and Monitoring	No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors	No No
3502 Hayes Road Monroe, NC 28112  Comparing Line Leak Detector Testing:	pliance Te	Fax (704) 845-4012  Website grienv.com  sting and Monitoring  Overfill Prevention Equipment Operability Check:		Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	
3502 Hayes Road Monroe, NC 28112  Comparing Line Leak Detector Testing: Containment Sump Testing:	pliance Tes No No	Fax (704) 845-4012  Website grienv.com  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	No
3502 Hayes Road Monroe, NC 28112  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Fax (704) 845-4012  Website grienv.com  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
3502 Hayes Road Monroe, NC 28112  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Fax (704) 845-4012  Website grienv.com  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
3502 Hayes Road Monroe, NC 28112  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Fax (704) 845-4012  Website grienv.com  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
3502 Hayes Road Monroe, NC 28112  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Fax (704) 845-4012  Website grienv.com  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
3502 Hayes Road Monroe, NC 28112  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Fax (704) 845-4012  Website grienv.com  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
3502 Hayes Road Monroe, NC 28112  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Fax (704) 845-4012  Website grienv.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
3502 Hayes Road Monroe, NC 28112  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax (704) 845-4012  Website grienv.com  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
3502 Hayes Road Monroe, NC 28112  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release:	No N	Fax (704) 845-4012  Website grienv.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Ital Service Firms  UST Compliance Consultants:	No No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
3502 Hayes Road Monroe, NC 28112  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Fax (704) 845-4012  Website grienv.com  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company		Listing Submitte	d 10/26/2021	Area of state conducts work	
Guardian Fueling Technologies	P	hone (919) 729-6980		Coastal (East of I-95): Yes	i
5116 Departure Drive		Fax (919) 769-2919		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27616		(0.0) . 00 20.0		Mountains (West of I-77): No	
	Wek	bsite <u>www.guardianfueltech.com</u>		Modificants (West of 1-17). No	
Comp	oliance Testin	g and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No C	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u> S	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No T	ank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No U	JST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u> U	JST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u> C	Other: SafeGuard UST Inspection	Services	UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmental \$	Service Firms		Other: FuelGuard fuel polishing / tank	cleaning
Emergency Cleanup - Spill/Release:	No U	JST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No U	JST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No V	Vaste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No C	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	d 1/25/2022	Area of state conducts work	
HARCO Services LLC	P	hone (770) 917-8846		Coastal (East of I-95): Yes	)
PO Box 2347		Fax (770) 917-0921		Central (West of I-95 and East of I-77): Yes	:
Kennesaw, GA 30156		(170) 317-0321			
	Web	bsite <u>www.harcoservices.com</u>		Mountains (West of I-77): Yes	i
Comp	oliance Testin	g and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	NI				No
Containment Sump Testing:	No C	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	140
Containment Cump resting.		Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S				
	No S No S	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S No S No T	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No S No S No T No U	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing:	No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No S No S No T No U	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No S No S No T No U	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No <u>Yes</u>
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S No T No U No U	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No <u>Yes</u> <u>Yes</u>
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S No T No U No U No C No nvironmental \$	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S No T No U No O No O No No O No O  Invironmental \$ No U	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release:	No S No T No U No O	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:  JST Internal Inspections (Integrity Assessments): JST Internal Lining Inspections: Other:  Service Firms  JST Compliance Consultants:	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No S No T No U No C No No C No No C No C No C No C No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing:  JST Internal Inspections (Integrity Assessments):  JST Internal Lining Inspections:  Other:  Service Firms  JST Compliance Consultants:  JST Equipment Verification:	No No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>

Company		Listing Submitted		Area of state conducts work	
Jones Covey Group	F	Phone (888) 972-7581		Coastal (East of I-95): Yes	
9595 Lucas Ranch Rd STE 100		Fax (909) 484-0300		Central (West of I-95 and East of I-77): Yes	
Rancho Cucamonga, CA 91730		(666) 16 1 6666		Mountains (West of I-77): Yes	
	We	ebsite		mountains (West of 1-77). Tes	
Comp	oliance Testir	ng and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<del></del>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/18/2020	Area of state conducts work	
Law Petroleum, Inc.	F	Phone (704) 573-3535		Coastal (East of I-95): Yes	
11025 Arlington Church Road		Fax (704) 573-3535		Central (West of I-95 and East of I-77): Yes	
Charlotte, NC 28227		( 1 , 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Mountains (West of I-77): Yes	
	We	ebsite		mountains (West of 1-77).	
Comp	oliance Testir	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
	Yes			UST System Removal:	<u>Yes</u>
Line Tightness Testing:	162			Other:	
		Service Firms			
	nvironmental	UST Compliance Consultants:	Yes		
Er	nvironmental Yes		Yes Yes		
Emergency Cleanup - Spill/Release:	nvironmental Yes No	UST Compliance Consultants:			
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	nvironmental Yes No No	UST Compliance Consultants: UST Equipment Verification:	<u>Yes</u>		

Company		Listing Submitte	d 8/3/2020	Area of state conducts work	
MECO, Inc. of Florence	Pho	ne (910) 223-0018		Coastal (East of I-95): Yes	
316 Raymond Street Fayetteville, NC 28301	F	ax (910) 223-0022		Central (West of I-95 and East of I-77): Yes	
	Websi	te www.mecoflorence.com		Mountains (West of I-77): No	
Comp	oliance Testing a	and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	Yes Ove	rfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	Yes Stat	istical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No Spil	Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No Tan	k Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No UST	Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	Yes UST	Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	Yes Other	er:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental Se	rvice Firms		Other:	
Emergency Cleanup - Spill/Release:	No UST	Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No UST	Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No Was	ste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Othe	er:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	d 2/28/2022	Area of state conducts work	
Parliament Petroleum Services LLC	Pho	ne (864) 871-8058		Coastal (East of I-95): No	
3277 Neely Ferry Rd		ax		Central (West of I-95 and East of I-77): No	
Laurens, SC 29360		ax		Central (West of 1-33 and Last of 1-77). No	
	Websi	te Parliamentpetroleumservices.com		Mountains (West of I-77): Yes	
		•		Mountains (West of I-77): Yes  UST Equipmment Service Contractors	
	Websi	•	No		Yes
Сотр	Websi	and Monitoring	No No	UST Equipmment Service Contractors	Yes Yes
Comp Automatic Line Leak Detector Testing:	Websi pliance Testing a No Ove No Stat	and Monitoring  rfill Prevention Equipment Operability Check:		UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	Websi pliance Testing a No Ove No Stat No Spil	rfill Prevention Equipment Operability Check: istical Iventory Reconciliation Services:	No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No Ove No Stat No Spil No Tan	rfill Prevention Equipment Operability Check: istical Iventory Reconciliation Services:  Prevention Equipment Testing:	No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No Ove No Stat No Spil No Tan No UST	rfill Prevention Equipment Operability Check: istical Iventory Reconciliation Services: Prevention Equipment Testing: k Tightness Testing:	No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Ove No Stat No Spil No Tan No UST	rfill Prevention Equipment Operability Check: istical Iventory Reconciliation Services:  Prevention Equipment Testing:  k Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Ove No Stat No Spil No Tan No US1 No US1	rfill Prevention Equipment Operability Check: istical Iventory Reconciliation Services:  Prevention Equipment Testing:  k Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Ove No Stat No Spil No Tan No UST No Oth	rfill Prevention Equipment Operability Check: istical Iventory Reconciliation Services: I Prevention Equipment Testing: k Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: er:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Ove No Stat No Spil No Tan No UST No Oth No Oth No Oth No	rfill Prevention Equipment Operability Check: istical Iventory Reconciliation Services: Prevention Equipment Testing: k Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: er:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En	No Ove No Stat No Spil No Tan No UST No Othe No Othe No Othe No UST	rfill Prevention Equipment Operability Check: istical Iventory Reconciliation Services: Prevention Equipment Testing: k Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: er:  rvice Firms Compliance Consultants:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Ove No Stat No Spil No Tan No UST No Othe No Othe No UST	rfill Prevention Equipment Operability Check: istical Iventory Reconciliation Services: Prevention Equipment Testing: k Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: er:  rvice Firms Compliance Consultants: Equipment Verification:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En	No Ove No Stat No Spil No Tan No UST No Othe No Othe No UST	rfill Prevention Equipment Operability Check: istical Iventory Reconciliation Services: I Prevention Equipment Testing: k Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: er:  rvice Firms Compliance Consultants: Equipment Verification: ste Disposal and Treatment:	No No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes

Company		7 LIGE (7 III) - GG	Listing Submitted	12/30/2021	Area of state conducts work	
Petroleum Equipment and Service, Inc.	Ph	one (704) 335-8801			Coastal (East of I-95): No	
4125 Sinclair Street		Fax (704) 342-1672			Central (West of I-95 and East of I-77): Yes	
PO Box 1949		( )			Mountains (West of I-77): Yes	
Denver, NC 28037	Web	site <u>www.petroleumequ</u>	<u>ipment.net</u>		Modificants (West of 1-17). 163	
Comp	oliance Testing	and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes O	verfill Prevention Equipment (	Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	Yes St	atistical Iventory Reconciliation	on Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:		oill Prevention Equipment Tes	sting:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		ank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:		ST Internal Inspections (Integ	•	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	Yes U	ST Internal Lining Inspections	3:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	Yes O	ther:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	<u>Yes</u>
Er	nvironmental S	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No U	ST Compliance Consultants:		No		
Environmental Engineer/Geologist - Site Checks:	No U	ST Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	No W	aste Disposal and Treatment	t:	<u>Yes</u>		
Oil and Solvent Recycling:	No O	ther:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	8/18/2020	Area of state conducts work	
Petroleum Service & Calibration, Inc.	Ph	one (704) 489-1671			Coastal (East of I-95): Yes	
7973 Vista View Drive		Fax (704) 489-1672			Central (West of I-95 and East of I-77): Yes	
Sherrills Ford, NC 28673		()			Mountains (West of I-77): No	
	Web	site <u>www.petroleumtank</u>	ktesting.com		Wouldains (West of 1-77). No	
Comp	oliance Testing	and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes O	verfill Prevention Equipment (	Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	Yes St	atistical Iventory Reconciliation	on Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No S	oill Prevention Equipment Tes	sting:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Ta	ank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes U	ST Internal Inspections (Integ	rity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes U	ST Internal Lining Inspections	s:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes O	ther:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Fr	nvironmental S	ervice Firms			Other:	
EI C				No		
Emergency Cleanup - Spill/Release:	No U	ST Compliance Consultants:		INU		
		ST Compliance Consultants: ST Equipment Verification:		No		
Emergency Cleanup - Spill/Release:	No U					
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No US	ST Equipment Verification:		No		

Company		Listing Submitted		Area of state conducts work	
Petroleum Solutions Inc.	Ph	ione (919) 605-1979		Coastal (East of I-95): Yes	
3012 Whitehart Ln.		Fax (919) 773-1704		Central (West of I-95 and East of I-77): Yes	
819 Purser Drive		(616) 116 1161		Mountains (West of I-77): No	
Raleigh, NC 27606	Web	site <u>www.petroleumsolutionsinc.net</u>		Mountains (West of 1-77): No	
Comp	oliance Testing	and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No O	verfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes St	atistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	pill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No Ta	ank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No U	ST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No U	ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No O	ther:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental S	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No U:	ST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No U	ST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No W	aste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No O	ther:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	7/30/2020	Area of state conducts work	
Pilot Geological, PLLC	Ph	one (336) 310-4527		Coastal (East of I-95): Yes	
743 Park Lawn Court		Fax (336) 310-4527		Central (West of I-95 and East of I-77): Yes	
PO 128		(666) 6.6 .62.			
Kernersville, NC 27285	Web	site <u>www.pilotenviro.com</u>		Mountains (West of I-77): Yes	
Comp	oliance Testing	and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No O	verfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No St	atistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No.	pill Prevention Equipment Testing:	NI -	Spill Bucket Installation Repair:	No
	No S	on Frevention Equipment resting.	No	- p	
Corrosion Protection System Repairs:		ank Tightness Testing:	No No	UST Equipment Installation - Other:	No
Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Ta				No No
	No Ta	ank Tightness Testing:	No	UST Equipment Installation - Other:	
Corrosion Protection System Testing:	No Ta No Us No Us	ank Tightness Testing: ST Internal Inspections (Integrity Assessments):	No No	UST Equipment Installation - Other: UST Equipment Repair:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Ta No Us No Us	ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections:	No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Ta No Us No Us No O	ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther:	No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Ta No Us No Us No Os No Os No nvironmental S	ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther:	No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Ta No Us No O No O No O nvironmental S	ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther: Service Firms	No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release:	No         Ta           No         Us           No         Us           No         Or           No         Or           no         Or           Yes         Us           Yes         Us	ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther:  Service Firms ST Compliance Consultants:	No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No         Ta           No         Us           No         Us           No         Os           Yes         Us           Yes         Us           Yes         W	ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther:  Service Firms ST Compliance Consultants: ST Equipment Verification:	No No No Yes Yes	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No

Company			• •	10/12/2022	Area of state conducts work	
Practical Environmental Solutions. PC	Р	hone (910) 790-8265			Coastal (East of I-95): Yes	
5634 Harvest Grove Ln		Fax			Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28409					Mountains (West of I-77): No	
	We	osite <u>www.oil-tank.com</u>			mountains (west of 1-17). No	
Comp	oliance Testin	g and Monitoring			<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No (	Overfill Prevention Equipment Operal	bility Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	Statistical Iventory Reconciliation Ser	vices:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No 7	ank Tightness Testing:	]	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No L	JST Internal Inspections (Integrity As	ssessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No L	JST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No (	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No L	JST Compliance Consultants:		No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	JST Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu		Vaste Disposal and Treatment:		No		
Oil and Solvent Recycling:		Other:				
Soil and Water Testing Lab:	<u>Yes</u>					
Company		Lis	ting Submitted	12/30/2021	Area of state conducts work	
Precision Tank Service	Р	hone (704) 892-8600			Coastal (East of I-95): Yes	
737 Zimmer Road		Fax (704) 892-8711			Central (West of I-95 and East of I-77): Yes	
Fort Mill , SC 29707		,				
					Mountains (West of I=//): Yes	
	We	osite <u>www.precisiontankservic</u>	e.com		Mountains (West of I-77): Yes	
Comp		psite www.precisiontankservic g and Monitoring	e.com		UST Equipmment Service Contractors	
Comp  Automatic Line Leak Detector Testing:	oliance Testin	•		Yes	·	No
_	oliance Testin	g and Monitoring	bility Check:	Yes No	UST Equipmment Service Contractors	No No
Automatic Line Leak Detector Testing:	Yes S	g and Monitoring  Overfill Prevention Equipment Operal	bility Check:		UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes S No S	g and Monitoring  Dverfill Prevention Equipment Operal Statistical Iventory Reconciliation Ser Spill Prevention Equipment Testing:  Tank Tightness Testing:	bility Check: vices:	No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes S No S	g and Monitoring  Overfill Prevention Equipment Operal Statistical Iventory Reconciliation Ser  Spill Prevention Equipment Testing:	bility Check: vices:	No <b>Yes</b>	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes S No S No T	g and Monitoring  Dverfill Prevention Equipment Operal Statistical Iventory Reconciliation Ser Spill Prevention Equipment Testing:  Tank Tightness Testing:	bility Check: vices:	No <u>Yes</u> <u>Yes</u>	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes S No S No T Yes U Yes U Yes U Yes U	g and Monitoring  Overfill Prevention Equipment Operal Statistical Iventory Reconciliation Ser Spill Prevention Equipment Testing: Fank Tightness Testing:  UST Internal Inspections (Integrity As	bility Check: vices:	No <u>Yes</u> <u>Yes</u> No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes S No S No Yes U Yes U Yes U Yes U Yes U	g and Monitoring  Overfill Prevention Equipment Operal Statistical Iventory Reconciliation Ser Spill Prevention Equipment Testing: Tank Tightness Testing:  UST Internal Inspections (Integrity As	bility Check: vices:	No <u>Yes</u> <u>Yes</u> No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No <u>Yes</u> No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes ( Yes ( Yes ( No ( Yes ( No ( Yes ( Ye	g and Monitoring  Overfill Prevention Equipment Operal Statistical Iventory Reconciliation Ser Spill Prevention Equipment Testing: Tank Tightness Testing:  UST Internal Inspections (Integrity As	bility Check: vices:	No <u>Yes</u> <u>Yes</u> No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No <u>Yes</u> No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Control Yes Co	g and Monitoring  Dverfill Prevention Equipment Operal Statistical Iventory Reconciliation Ser Spill Prevention Equipment Testing: Tank Tightness Testing:  JST Internal Inspections (Integrity As JST Internal Lining Inspections:  Other:	bility Check: vices: ssessments):	No Yes Yes No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No <u>Yes</u> No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes S No S No S Yes S Yes S No S No S No S Yes S Yes S Yes S Yes S Yes S No S Yes S Yes S Yes S No	g and Monitoring Diverfill Prevention Equipment Operal Statistical Iventory Reconciliation Ser Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity As UST Internal Lining Inspections: Dither:	bility Check: vices: ssessments):	No <u>Yes</u> <u>Yes</u> No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No <u>Yes</u> No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	Yes Control Yes Co	g and Monitoring Deerfill Prevention Equipment Operal Statistical Iventory Reconciliation Ser Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity As UST Internal Lining Inspections: Dether:  Service Firms UST Compliance Consultants:	bility Check: vices: ssessments):	No Yes Yes No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No <u>Yes</u> No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Control of the co	g and Monitoring  Diverfill Prevention Equipment Operal Statistical Iventory Reconciliation Ser Spill Prevention Equipment Testing: Fank Tightness Testing:  UST Internal Inspections (Integrity As UST Internal Lining Inspections:  Dither:  Service Firms  UST Compliance Consultants:  UST Equipment Verification:	bility Check: vices: ssessments):	No Yes Yes No No Yes No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No <u>Yes</u> No No

Company		Listing Submitte	d 1/3/2022	Area of state conducts work	
Pyramid Environmental & Engineering, PC	Phon	e (336) 335-3174		Coastal (East of I-95): Yes	
503 Industrial Avenue Greensboro, NC 27406	Fa	ix (336) 691-0648		Central (West of I-95 and East of I-77): Yes	
	Websit	e www.PyramidEnvironmental.com		Mountains (West of I-77): Yes	
Comp	liance Testing ar	nd Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Over	fill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Statis	stical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spill	Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tank	Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No UST	Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No UST	Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Othe	r:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	vironmental Serv	vice Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes UST	Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes UST	Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes Wast	e Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No Othe	r:			
Soil and Water Testing Lab:	<u>Yes</u>				
Commons		Hada o Later			
Company		Listing Submitte	d 9/14/2020	Area of state conducts work	
Schnabel Engineering Sourh, P.C.	Phon	Listing Submitted	d 9/14/2020	Area of state conducts work  Coastal (East of I-95): Yes	
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205	Phon Fa	e (910) 769-1621	d 9/14/2020		
Schnabel Engineering Sourh, P.C.	Fa	ue (910) 769-1621	d 9/14/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205		ue (910) 769-1621	d 9/14/2020	Coastal (East of I-95): Yes	
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401	Fa	e (910) 769-1621  www.schnabel-eng.com	d 9/14/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401	Fa Websit liance Testing an	e (910) 769-1621  www.schnabel-eng.com	No 9/14/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401	Websit  Websit  Websit  Oliance Testing and  No Over	e www.schnabel-eng.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Websit  Valiance Testing at  No Over  No Statis  No Spill	e www.schnabel-eng.com  nd Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services:  Prevention Equipment Testing:	No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:	No
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Websit  Valiance Testing and  No Overl  No Statis  No Spill  No Tank	e www.schnabel-eng.com  nd Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing:	No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:  UST Equipment Installation - Other:	No No
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Websit  Valiance Testing and No Overling No Statis  No Spill  No Tank  No UST	e www.schnabel-eng.com  Ind Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Websit  Valiance Testing and No Overling No Statis  No Spill  No Tank  No UST	e www.schnabel-eng.com  nd Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Websit  Valiance Testing and No Overling No Statis  No Spill  No Tank  No UST	e www.schnabel-eng.com  Ind Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Websit  Voliance Testing and No Overling No Statis  No Spill  No Tank  No UST  No UST	e www.schnabel-eng.com  Ind Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Websit  Voliance Testing and No Overl No Statis No Spill No Tank No UST No UST No Other	e www.schnabel-eng.com  Ind Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: T:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Websit  Viliance Testing and No Overling No Statis No Spill No Tank No UST No UST No Other	e www.schnabel-eng.com  Ind Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: T:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Websit  Valiance Testing and No Overling No Statis No Spill No Tank No UST No UST No Other	e www.schnabel-eng.com  Ind Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: r:  vice Firms	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release:	Websit  Voliance Testing and No Overling No Statis No Spill No Tank No UST No UST No Other No Other No Other No Other No Other Yes UST Yes UST	e www.schnabel-eng.com  nd Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: r:  vice Firms  Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Schnabel Engineering Sourh, P.C. 244 Princess Street, Suite 205 Wilmington, NC 28401  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Websit  Voliance Testing and No Overling No Statis No Spill No Tank No UST No UST No UST No Other No Other No Other No Other Yes UST Yes UST	e www.schnabel-eng.com  Ind Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: r:  vice Firms  Compliance Consultants: Equipment Verification: te Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

Company		Listing Submitted	6/29/2021	Area of state conducts work	
SR&R Environmental, Inc.	P	Phone (910) 763-6274		Coastal (East of I-95): Yes	
4920 Highway 421 N.		Fax (910) 763-6132		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28401-		(0.10) 1.00 0.102		Mountains (West of I-77): No	
	We	bsite <u>www.srrenviro.com</u>		Wouldains (West of 1-77). No	
Comp	oliance Testin	ng and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No (	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No l	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No l	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No (	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes l	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:		Other: Vacuum Truck	Services		
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/13/2020	Area of state conducts work	
Unified Services of Texas	P	Phone (817) 481-9510		Coastal (East of I-95): Yes	
2110 Greenbriar dr.	_	Fax		Central (West of I-95 and East of I-77): Yes	
Southlake, TX 76092		rax			
	Wa	helte ueffuel com		Mountains (West of I-77): Yes	
	AAG	bsite <u>ustfuel.com</u>			
Comp				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	oliance Testin	ng and Monitoring Overfill Prevention Equipment Operability Check:	<u>Yes</u>	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	No
Automatic Line Leak Detector Testing:	oliance Testin	ng and Monitoring Overfill Prevention Equipment Operability Check:	Yes Yes	Dispenser Meter Repair/Calibration:	
_	Oliance Testin  Yes  Yes	ng and Monitoring	Yes Yes Yes		No <u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing:	Yes S	ng and Monitoring  Overfill Prevention Equipment Operability Check:  Statistical Iventory Reconciliation Services:  Spill Prevention Equipment Testing:	<u>Yes</u> <u>Yes</u>	Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Yes S No S	ng and Monitoring  Overfill Prevention Equipment Operability Check:  Statistical Iventory Reconciliation Services:	<u>Yes</u> <u>Yes</u> <u>Yes</u>	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes S No S No N	og and Monitoring  Overfill Prevention Equipment Operability Check:  Statistical Iventory Reconciliation Services:  Spill Prevention Equipment Testing:  Tank Tightness Testing:	<u>Yes</u> <u>Yes</u>	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Colliance Testin	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes Yes Yes Yes	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes S No S No No No No Yes S	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes Yes Yes Yes	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes ( Yes ( Yes ( No ( No ( Yes ( Ye	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes Yes Yes Yes	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes ( Yes ( No ( No ( Yes ( Yes ( No ( Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms	Yes Yes Yes Yes Yes	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	Yes ( Yes ( No ( Yes ( No ( Yes ( Ye	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants:	Yes Yes Yes Yes Yes Yes	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes No No Yes Yes Ves Yes Yes Yes Yes No Yes Yes Yes No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms	Yes Yes Yes Yes Yes	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes ( Yes ( Yes ( No ( No ( Yes ( Ye	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes Yes Yes Yes Yes Yes Yes	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes

Company	O I TOVIGO		ing Submitted	1/31/2023	Area of state conducts work	
Valor Construction LLC	Pho	ne (205) 577-1035			Coastal (East of I-95): Yes	
PO Box 680654		ax			Central (West of I-95 and East of I-77): Yes	
Fort Payne, AL 35968					Mountains (West of I-77): Yes	
	Webs	te			Mountains (West of 1-77): Tes	
Comp	oliance Testing a	and Monitoring			<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No Ove	rfill Prevention Equipment Operabi	ility Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Star	istical Iventory Reconciliation Serv	rices:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spil	Prevention Equipment Testing:		No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tan	k Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		Internal Inspections (Integrity Ass	sessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No US	Internal Lining Inspections:		No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No Oth	er:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmental Se	rvice Firms			Other:	
Emergency Cleanup - Spill/Release:	No US	Compliance Consultants:		No		
Environmental Engineer/Geologist - Site Checks:	No US	Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	No Wa	ste Disposal and Treatment:		No		
Oil and Solvent Recycling:	No Oth	er:				
Soil and Water Testing Lab:	No					
Company		Listi	ing Submitted	10/5/2021	Area of state conducts work	
VITAL FUEL SYSTEMS INC.	Pho	ne (919) 303-7374			Coastal (East of I-95): Yes	
1076 CLASSIC ROAD	F	ax (919) 303-7399			Central (West of I-95 and East of I-77): Yes	
APEX, NC 27540		(0.10) 000 1000			Mountains (West of I-77): Yes	
	Webs	te <u>WWW.VITALFUELSYSTE</u>	EMS.COM		would all s (west of 1-77). Tes	
Comp	oliance Testing a	and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Ove	rfill Prevention Equipment Operabi	ility Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Stat	istical Iventory Reconciliation Serv	rices:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No Spil	Prevention Equipment Testing:		No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		k Tightness Testing:		No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No US	Internal Inspections (Integrity Ass	sessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No US	Internal Lining Inspections:		No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No Oth	er:			UST Piping/Sump Installation:	<u>Yes</u>
					UST System Removal:	<u>Yes</u>
Line Tightness Testing:	No					
	No nvironmental Se	rvice Firms			Other:	
	nvironmental Se	rvice Firms Compliance Consultants:		No	Other:	
Er	No US			No No	Other:	
Emergency Cleanup - Spill/Release:	No US	Compliance Consultants:			Other:	
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No US	Compliance Consultants: Equipment Verification: ste Disposal and Treatment:		No	Other:	

Company		Listing S	Submitted	2/5/2021	Area of state conducts work	
Wildco PES		Phone (603) 935-9330			Coastal (East of I-95): Yes	
440 Harvey Rd		Fax			Central (West of I-95 and East of I-77): Yes	
497 Lendall Lane Fredericksburg VA 22405		T un			Mountains (West of I-77): No	
Manchester, NH 3103	V	Vebsite WILDCOPES.COM			Mountains (West of 1-77). No	
Comp	oliance Tes	ting and Monitoring			<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability C	heck: Ye	es es	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	)	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Y</u> e	e <u>s</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Y</u> e	e <u>s</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessm	nents): No	)	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	)	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Ye	es		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Ye	es		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No			
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company		Listing §	Submitted	8/13/2020	Area of state conducts work	
WithersRavenel, Inc.		Phone (919) 469-3340			Coastal (East of I-95): Yes	
115 MacKenan Drive		Fax			Central (West of I-95 and East of I-77): Yes	
Cary, NC 27511					Mountains (West of I-77): Yes	
	V	Vebsite <u>www.withersravenel.com</u>			mountains (West St 177).	
Comp		Vebsite www.withersravenel.com ting and Monitoring			UST Equipmment Service Contractors	
Comp Automatic Line Leak Detector Testing:			heck: No	)	· · ·	No
	pliance Tes	ting and Monitoring	heck: No		UST Equipmment Service Contractors	No No
Automatic Line Leak Detector Testing:	pliance Tes	ting and Monitoring  Overfill Prevention Equipment Operability C			UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	ting and Monitoring  Overfill Prevention Equipment Operability C Statistical Iventory Reconciliation Services:	No	) )	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	ting and Monitoring  Overfill Prevention Equipment Operability C Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No		UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No	ting and Monitoring  Overfill Prevention Equipment Operability C Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No		UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Overfill Prevention Equipment Operability C Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessm	No No nents): No		UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Overfill Prevention Equipment Operability C Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity AssessmuST Internal Lining Inspections:	No No nents): No		UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability C Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity AssessmuST Internal Lining Inspections:	No No nents): No		UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability C Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessm UST Internal Lining Inspections: Other:	No No nents): No		UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability C Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessm UST Internal Lining Inspections: Other:	No No No nents): No	) ) ) )	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En	No N	Overfill Prevention Equipment Operability C Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessm UST Internal Lining Inspections: Other:  al Service Firms UST Compliance Consultants:	No No nents): No No	) ) ) ) )	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Overfill Prevention Equipment Operability C Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessm UST Internal Lining Inspections: Other:  al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No nents): No No	25 25 25 25 25	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No